Oil Field Environmental Incident Summary

Incident: 20140516090644   *Date/Time of Notice:* 05/16/2014   09:06

Responsible Party: WHITING OIL AND GAS CORPORATION

Well Operator: WHITING OIL AND GAS CORPORATION

Well Name: JOHNSON 34-8H

Field Name: PLEASANT HILL   *Well File #:* 19847

Date Incident: **5/15/2014**   *Time Incident:* 16:00   *Facility ID Number:*

County: MCKENZIE   *Twp:* 149 *Rng:* 99 *Sec:* 8 *Qtr:* SE SW

Location Description: just off constructed well site, to the south by southeast.

Submitted By: Adam Rookey   *Received By:*

Contact Person: Mitch Haugeberg
                    1700 BROADWAY STE 2300
                    DENVER, CO 80290

General Land Use: Cultivated   *Affected Medium:* Topsoil

Distance Nearest Occupied Building: 0.5 Mile
Distance Nearest Water Well: 0.5 Mile

Type of Incident: Other

Release Contained in Dike: No   *Reported to NRC:* No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0.2	Barrels				
Brine						
Other						

Description of Other Released Contaminant:

Inspected: *Written Report Received:* 1/11/2016   *Clean Up Concluded:* 2/28/2014

Risk Evaluation:
to be determined

Areal Extent:
to be determined

Potential Environmental Impacts:

to be determined

Action Taken or Planned:

Line cleared of oil. Checked dump valves. Impacted material material will be collected and properly disposed.

Wastes Disposal Location: at an appropriate waste disposal facility

Agencies Involved:

Updates

Date: 5/16/2014   ***Status:*** Reviewed - Follow-up Required   ***Author:*** Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release from an unspecified cause sprayed off location. Followup is necessary.

Date: 5/23/2014   ***Status:*** Inspection   ***Author:*** Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

2/23/14 - 09:55 on location. Called company contact to learn more about release. His impression was that it had all remained on location, near the flare stack which had been the discharge point. Confirmed by inspection. No staining of vegetation or soil off location around the flare stack (S and SW). No further inspection needed.